



Cargador rápido GAL 18 V-160 AS

Tiempos de carga cortos gracias a la elevada corriente de carga de 16 amperios, el modo de carga Power Boost, la refrigeración de aire activa y la gestión de carga controlada por proceso. Con indicador de nivel de carga y dispositivo para montaje en la pared. Para todos los equipos a batería con alojamiento para la batería AMPShare o Bosch Professional de 18 V. Tiempos de carga (80 % de la capacidad máx.): GBA 18 V 2.0 Ah: 15 min., GBA 18 V 4.0 Ah: 16 min., GBA 18 V 5.0 Ah: 20 min., ProCORE 18 V 4.0 Ah: 32 min., ProCORE 18 V 8.0 Ah: 32 min., ProCORE 18 V 12.0 Ah: 36 min.

129,00 € P.V.P. sin I.V.A.

N.º pedido: 9 26 04 339 01 0

Adaptable para las siguientes máquinas

Taladro atornillador con acumulador

- > ASCM 18-4 QMP AS
- > ASCM 18-4 QM AS Set 5 Ah
- > ASB 18 Q AS Set 5 Ah
- > ASCM 18-4 QM AS
- > ASCM 18 QSW AS Set 5 Ah
- > ABS 18 Q AS Set 5 Ah
- > ASB 18 Q AS
- > ASCM 18-4 QM AS
- > ASCM 18 QSW AS
- > ABS 18 Q AS

Amoladora angular (Premium)

- > CCG 18-115-10 PD-SEC Set 8Ah ProCORE AS
- > CCG 18-115-10 PD-SEC AS
- > CCG 18-125-10 PD-SEC AS
- > CCG 18-125-10 AS
- > CCG 18-125-10 PD AS
- > CCG 18-115-10 PD AS
- > CCG 18-115-10 AS
- > CCG 18-125-10 PD-SEC Set 8Ah ProCORE AS

Universal

- > AKBU 35 PMQW 18 V AS Construction-Site 2x 8 Ah Set 3/4 in Weldon / HSS NOVA 50
- > AKBU 35 PMQW 18 V AS Construction-Site 1x 12 Ah Set 3/4 in Weldon / HSS NOVA 50
- > AKBU 35 PMQW AS Construction-Site Set 3/4 in Weldon / HSS NOVA 50
- > AKBU 35 PMQW 18 V AS Set 1x 12 Ah
- > AKBU 35 PMQW 18 V AS Set 2x 8 Ah
- > AKBU 35 PMQW AS
- > AKBU 35 PMQ AS

Llave de impacto a batería

- > ASCD 18-300 W2 AS
- > ASCD 18-300 W2 AS Ready to-use-top Set
- > ASCD 18-200 W4 AS Set 5 Ah
- > ASCD 18-300 W2 AS Set 5 Ah
- > ASCD 18-200 W4 AS
- > ASCD 18-300 W2 AS Ready-to-use Set

Biselado

- > Set básico para biselado AKFH 18-5 AS con 1 batería 8 Ah ProCore
- > AKFH 18-5 AS
- > Set básico para biselado AKFH 18-5 AS
- > Set básico para biselado AKFH 18-5 AS con 2 baterías 8 Ah ProCore

Rectificadora recta

- > AGSZ 18-90 LBL AS
- > AGSZ 18-280 LBL AS
- > AGSZ 18-280 BL AS

Sierra de cinta sin cable



FEIN

> ABAS 18-63 AS

> ABAS 18-63 AS Set 2 x 8

Ah

Sierra circular sin cable

> F-IRON Cut 57 AS Set 2 x

8 Ah

> F-IRON Cut 57 AS

Amoladora angular (Universal)

> CCG 18-125-15 AS

> CCG 18-125-7 AS

Taladro percutor a batería

> ABH 18-26 AS